

THE BHOPAL DISASTER

– learning from failures and evaluating risk

Abstract

The economic, technological and organizational errors attributable to the root causes of the Bhopal disaster of the 2nd and 3rd of December 1984 are identified. In particular, the technical causes of the failure from a design and operational perspective are highlighted. An investigation is then carried out to determine the major consequences of the failure. Fault Tree Analysis (FTA) and Reliability Block Diagrams (RBDs) are then used to model the causes, and determine the probability of occurrence, of the accident. The innovative aspect of this work is that whereas such techniques are usually employed at an equipment level they are used here to analyse a catastrophic event. Recommendations regarding emergency and contingency planning are then provided. It is concluded that, in future multi-national company (MNC) projects, designs of installations need to be peer reviewed and more stringent environmental, health and safety considerations adopted, and that governments need to be aware of the requirement for segregation of hazardous operations from facilities and adjacent domestic populations.

Keywords: Bhopal, Fault Tree Analysis, Reliability Block Diagrams



*Ashraf W.
Labib,
Portsmouth
Business
School,
University of
Portsmouth*



*Ramesh
Champaneri, School
of Engineering,
Science and
Design, Glasgow
Caledonian
University*

INTRODUCTION

In 1984 Bhopal city, located in the centre of India with a population of approximately 1.4 million, became one of the best known places in the world – but for all the wrong reasons. On December 3rd, when the town's people slept, the Union Carbide Pesticide Plant, about five miles away, unleashed 'hell on earth'. Poisonous gases were released into the atmosphere and killed some 3,000 people (up-to-date figures indicate 8,000 fatalities at the time and a further 12,000 since). These gases included one used in early World Wars that attacks the 'wet' parts of the body, such as the eyes, mouth and throat.

This particular gas then enters the lungs, where it reacts with bodily fluids, filling the lungs and drowning a person 'from the inside'. This was a disaster the town might eventually (over a long period of time and with help) have come to terms with, were it not for the following facts:

- The deaths did not stop at 3,000 – they are reputed to total 20,000 to date (see earlier) – and to this day approximately 120,000 people continue to suffer from the resulting serious ill health problems.
- 'It was an accident waiting to happen' – comparisons with the operation of similar plants in US and India indicate that the Bhopal plant was neglected to

say the least. Cost cutting measures were introduced at the cost of safety. The value of human life in India was not a priority

- The lies – management at the plant (none of whom died that night) commented that the gas was similar to tear gas and that the effects would fade in three days...some twenty years later the effects are still evident. Union Carbide Corporation and the Indian Government claimed, until 1994, that the gas Methyl Isocyanate (MIC) had no long term effects.
- A vast history of events (since 1976) leading up to the event had gone unheeded by the Corporation, and to this day they have not claimed full responsibility for any wrongdoing; nor does anyone sit in jail for the 'murder' of so many.
- Reports issued months prior to the incident by scientists within Union Carbide Corp. warned of the possibility of an accident almost identical to that which happened – reports which were ignored and were never delivered to senior staff.

The aim of the study reported here was to produce an objective Fault Tree which would help to identify what could be learned from this terrible incident and to show that it was indeed 'an accident waiting to happen', by –

- Discovering the technical causes of the failure from a design and operations perspective.
- Identifying the major consequences of the failure – then and today.
- Using a Fault Tree Analysis and Reliability Block Diagram analysis to determine the probability of such an occurrence happening.
- Recreating, using the Minimal Cut Set method, a 'new' Fault Tree Analysis.
- Setting recommendations regarding emergency and contingency planning.

BACKGROUND

In 1969, the multi-national corporation (MNC) Union Carbide (UC) established a small Indian subsidiary – Union Carbide India Ltd (UCIL) – to manufacture pesticides at Bhopal in India. The Indian plant offered competitive advantages because of its low labour costs, access to an established and rapidly growing market and lower operating costs. In addition UCIL was able to exploit India's lax environmental and safety regulations as the country strived to attract large MNCs for its developing industrialisation programme. Until 1979 UCIL imported Methyl Isocyanate (MIC), a key component in the production of pesticides, from its parent company, UC. The new Bhopal facility was advertised as being designed and built on the basis of twenty years of

experience with UC's MIC facility in West Virginia, USA.

Installation

As early as 1972 a UC internal report had recommended that if additional MIC plants were to be built they should be constructed of materials as good as those used on the West Virginia plant. It became clearly evident that although UC engineers oversaw the design, build and operation until the end of 1982 along with technical support and safety reviews, the Indian facility underwent cost-cutting programmes in design and construction which were not mirrored in comparable Western plants, viz.

- Carbon steel piping, which is more corrosive, replaced stainless steel piping.
- The number and quality of safety devices was reduced (a \$3-6 million saving).
- Installed safety devices in western plants were automatically controlled with back-up devices – at Bhopal they were manual.
- At similar Western plants computerised early warning systems sensed leaks, monitored their rates and concentrations and were linked to a telephone system to automatically dial out alerts – In Bhopal there were not even any emergency planning measures.
- At Bhopal one vent gas scrubber (VGS) was installed, resulting in no redundancy. The equivalent plant in the USA had four VGSs.
- At Bhopal only one flare tower was installed, i.e. no redundancy. The equivalent plant in the USA had two.
- In Bhopal, no unit storage tank between MIC manufacture and main storage tank was installed to check for purity. This was designed in and installed on the US plant.

None of the six main safety features of the plant were efficient due to design but also on the night of the incident, none were operational due to an under pressure maintenance schedule (due to under staffing).

At the local level, no emergency planning was undertaken prior to the commissioning of the plant. In the US emergency planning had been essential and had involved all of the emergency services and a public broadcasting system.

Prior to the disaster, operating incidents resulting in plant workers being killed or injured, and minor amounts of toxic gases being released, had caused UC to send, in May 1982, a team of US experts to inspect the Bhopal plant as part of a safety audit. Their report, which was passed to UC's

management in the USA indicated that there was – *"a serious potential for sizeable releases of toxic materials in the MIC unit either due to equipment failure, operating problems or maintenance problem, thus requiring various changes to reduce the danger of the plant. There is no evidence that the recommendations were ever implemented"* [1].

Precursors leading to the disaster

Prior to the disaster, both training, manning levels and the educational standards of the employees of the plant workforce were reduced. Between 1980 and 1984, the plants workforce was reduced by half with no clear investment in technology to warrant this reduction

The basic operation of the plant was further compromised by management decisions to operate the plant either outside its designed operating parameters or to implement revised processes to ensure continued production while essential components of the system had known defects which had the potential to impact on the safety integrity of the plant.

DIRECT CAUSES OF THE ACCIDENT

The production of a deadly cloud of MIC was produced as a consequence of a cheap engineering solution to a known maintenance problem. A "jumper line" connected a relief valve header to a pressure vent header enabling water from a routine washing operation to pass to MIC storage tank 610. The ingress of water to the MIC tank created an uncontrollable runaway exothermic reaction. The reaction products passed through the process vent header to the jumper line, to the relief valve vent header, onto the vent gas scrubber and finally to the atmosphere through the atmospheric vent line. The toxic gases were discharged for 2 hours 15 minutes.

The release of toxic gases was assisted by the following defects and lapses in standard operating procedures which could have easily been averted in many instances:

- MIC storage tank number 610 was filled beyond recommended capacity. Functional contents gauges should have provided warning of this and the process halted until rectified.
- A storage tank which was supposed to be held in reserve for excess MIC already contained MIC [2]. The reserve storage tank should have been empty and any production should have been halted until this requirement had been established. This should have been a formal requirement 'hold point' in the control process prior to production

being allowed to continue.

- The blow-down valve of the MIC 610 tank was known to be malfunctioning; consequentially it was permanently open. This valve should have been repaired or the tank should have been removed from service until repaired.
- The danger alarm sirens used for warning the adjacent residential communities were switched off after five minutes in accordance with revised company safety practices. This clearly highlights why the site required emergency procedures to be in place and continually reviewed.
- The plant superintendent did not notify external agencies of the accident and initially denied the accident had occurred. This was clear negligence on behalf of the management but typified the poor health and safety culture within the plant.
- The civic authorities did not know what actions to take in light of there being no emergency procedures in place and were un-informed of the hazardous materials stored within the plant. The requirements for good communications and established emergency procedures with local agencies and emergency services highlighted these shortfalls.
- Gauges measuring temperature and pressure in the various parts of the facility, including the crucial MIC storage tanks, were so notoriously unreliable that workers ignored early signs [1]. The company should have had a robust maintenance regime which should have prevented this, coupled with a safety culture which should have questioned any unsafe conditions.
- The refrigeration unit for keeping MIC at low temperatures, and therefore making it less likely to undergo overheating and expansion should contamination enter the tank, had been shut off for some time [1]. This issue could have only been resolved by the management having a commitment to safety and process guarding as opposed to profit generation.

The failings below are attributable to design reductions and the fact that UCIL was able to dilute its safety protection devices in order to maximise profits, while any local peer reviews of designs by local safety/engineers were non-existent:

- The gas scrubber, designed to neutralize any escaping MIC, had been shut off for maintenance. Even had it been operative, post disaster inquiries revealed that the maximum pressure it could handle was only one quarter of that which was actually reached in the accident [1].
- The flare tower, designed to burn off MIC escaping from the scrubber, was also turned off, waiting for the replacement of a corroded piece of pipe. The tower, however, was inadequately designed for its task, as it

was capable of handling only a quarter of the volume of the gas released [1].

- The water curtain, designed to neutralise any remaining gas, was too short to reach the top of the flare tower where the MIC billowed out [1].
- There was a lack of effective warning systems; the alarm on the storage tank failed to signal the increase in temperature on the night of the disaster [2].

THEORY AND CALCULATION

Fault Tree Analysis (FTA) and a Reliability Block Diagram (RBD) have been used to map the root causes of the disaster and calculate its overall probability of occurrence, the RBD being derived from the FTA. The parallel and series connections in the RBD, which are derived from the AND and OR gates respectively of the FTA, describe how the system functions (or fails to function), but do not necessarily indicate any actual physical connection nor any sequence of operation. In other words, the RBD does not model the flow of material nor any sequence of time events, but instead models the inter-dependencies of the root causes that led to the failure mode at the apex of the Fault Tree.

There are many benefits derivable from an analysis based on FTA and RBD modelling. Firstly, it helps to highlight vulnerable, or weak, areas in the model that need attention in the form of adding, for example, built-in-testing, redundancy, or more preventive maintenance. Secondly, it acts as a knowledge-base of how a system fails and hence can be used for diagnostics or fault finding. Finally, given the value of availability of each 'box' in the RBD model it is possible to estimate the whole system's reliability – which is useful both when aiming to improve system reliability by preventing things from going wrong, and when aiming at system recovery by restoring elements that have failed.

Normally, we use FTA and RBD to model a failure mode at an equipment or machine level. Such a mode may, for example, be 'Motor A fails to start'. In this study, however, the same methods of analysis are applied on a larger scale, where the failure mode is the occurrence of a disastrous situation such as that at Bhopal. Here, there are two distinct features that need to be considered. Firstly, the situation is complex, influenced by a range of human, social and environmental factors which are difficult to evaluate. Secondly, the whole meaning of 'availability', in the context of modelling a disastrous situation, can be a matter of debate or even confusion. To pose a fundamental question: should we expect that the total availability of a plant to




Figure 1 Overall Fault Tree Analysis of the disaster

provide protection against a disaster be a low figure or a high one?

To attempt to answer this last seemingly simple question, one needs to go back to the fundamental definitions of the terms

involved. Availability is calculated as a function of both the frequency of a failure (i.e. the mean time between failures, a measure of reliability) and its severity (i.e. the mean time to repair, a measure of




Figure 2 Fault Tree of failure due to diminished design specifications

maintainability). Since a disaster is, by its very nature, a severe and yet a rare event, one would normally expect high figures for availability of protection against its occurrence - due to its very low frequency (a one-off event). However, this would

not be the case when the existing design and operation of the system is not fit for purpose, and hence it is a disaster waiting to happen, and in this situation one would expect that total system availability would be rather low.




Figure 3 Fault Tree of incorrect management decisions




Figure 4 Fault Tree of poor maintenance

Figure 1 shows the overall Fault Tree analysis.

Figures 2, 3 and 4 further extend the analysis of Figure 1.

The reliability block diagrams for each tree are then presented in Figure 5, and the overall reliability block diagram related to the disaster in Figure 6.

Table 1 (see pages 46-47) presents our estimated 'probabilities of failures' for the various contributory events discussed in the previous, 'Direct Causes', Section. Estimates of P_f (probability of systems failure) are used as a measure of unreliability – where the sum of P_f and P_s (probability of success) equals one as the system is either in a fault or running state. Again, 'probability' may here have different meanings, i.e. a measure of confidence or a measure of availability. Either way, we use it in this context to provide us with an indication of the relative importance (priority) of the various factors that led to the disaster. Note that the numbers labelling the various FTA events and/or RBD boxes in the figures refer to the numbers used to list the various events/factors listed in Table 1. It must be stressed that this is very much a speculative evaluation. It is suggested that using these data and applying straightforward Boolean analysis of the logic of the Fault Trees (which is beyond the scope of this paper) could form the basis of an informative estimate of the relative significance of the factors that may have contributed to the disaster.

DISCUSSION

UCIL had allowed safety standards and maintenance at the plant to deteriorate to cataclysmic levels even though the potential for such an incident had been highlighted two years prior in a UC internal report. Clearly UCIL had dropped the operating and safety standards of the Bhopal facility well below those maintained in the near identical facility in West Virginia. The fact that UCIL was able to do this was due in part to lacking safety and environmental laws and regulations which were not enforced by the Indian government. Immediately after the disaster in India, UC, while maintaining no knowledge of the cause of the accident in India, shut down the MIC plant in West Virginia to allow five million dollars worth of changes to its safety devices to be accomplished.

CONCLUSION

The Indian government, although keen to attract foreign investment, needed to factor in basic safety requirements for its citizens. During future MNC projects, designs of installations need to be peer reviewed and




Figure 5 Reliability Block Diagrams




Figure 6 Combined Reliability Diagram for the disaster

more stringent environmental, health and safety considerations adopted.

During any future plant builds, standards of materials and equipment used should reflect those used in Western countries. MNC need to be aware that reduction in safety standards as a means of improving profit margins is not an option in light of the disaster at Bhopal.

Governments need to be aware of the requirement for segregation of hazardous operations from facilities and

adjacent domestic populations. In the case of Bhopal the local communities and "squatter camps" should have been relocated prior to any company being given permission to start mass production of inherently dangerous substances.

A means of guarding operating processes, along with habitual safety checking, needs to be implemented and established as a corner stone of any safety culture within hazardous plants like Bhopal. The safety culture of any such plants needs to be developed so that questioning attitudes

are commended rather than chastised and safety is the optimum driver rather than profit motivation.

MNC need to re-instigate high levels of safety training to improve employees' awareness of hazards. In addition, the quality of the employees and staff numbers should not be reduced at the expense of safety to bolster company profits.

MNCs attracted to third world countries by the prospect of cheap labour costs and potentially less stringent environmental, health and safety legislation need to consider the adverse impact on their business brought about by focused media coverage resulting from perceived neglect to the health and safety of their workforce, which ultimately impacts on their company reputation.

The main significance of this work is that we demonstrate that learning can be addressed in three perspectives which are: (i) feedback from the users (maintenance) to design, (ii) the incorporation of advanced tools in innovative applications, and (iii) the fostering of interdisciplinary approaches and generic lessons. Our basic findings are therefore related to the feedback process through advice to both future MNC projects in terms of designs of installations, as well as recommendations to Governments in terms of health and safety considerations. We have incorporated tools such as fault tree analysis, reliability block diagrams and cut set calculations, which have helped us to develop an objective model to discover what can be learned from this terrible incident. In doing so, we have tried to develop a generic approach that can be used to learn from any future disasters. *

ACKNOWLEDGEMENTS:

We are grateful to John Unwin, Paul McGibney, and Mazen Al-Shanfari, who helped to collect the data for the case study. We are also grateful to Ms Rebecca Harris for the proof reading and editing of the manuscript.

REFERENCES

- [1] Weir D, The Bhopal Syndrome: Pesticides, Environment and Health. San Francisco 1987
- [2] Cassels J, The Uncertain Promise of Law: Lessons from Bhopal. University of Toronto Press 1993
- [3] Chouhan T, The Unfolding of the Bhopal Disaster, Journal of Loss Prevention in the Process Industries, Vol.18, pp 205–208. 2005

Table 1 continued on page 52

Continued from page 51

Event No.	Comments	$P_f = F / S + F$	Actual P_f Value
1 – Quality of employees reduced	Reduction of Operators with High school education over 5 years = 9	$= (9 / 6 + 15) / 43800$	9.6×10^{-6}
	No. of Operators with High school education at time of disaster = 6		
	No. of Operators with High school education in 1979 = 15		
	No. of hours for 5 year period = $24 \times 365 \times 5 = 43800$		
2 – Safety training of staff reduced	Original No. of training days = $18 \text{ months} \times 30 \text{ days} = 540$	$= (523/540 + 17) / 43800$	21.4×10^{-6}
	Reduction in training days during 5 year period = 523		
	No. of actual training days = 17		
	No. of hours for 5 year period = $24 \times 365 \times 5 = 43800$		
3 – Poor Health and Safety Culture	Assumption – health and safety culture dependent upon quality and training of staff	$= 9.6 \times 10^{-6} + 21.4 \times 10^{-6}$	31.1×10^{-6}
	Pf value = event 1 + 2		
4 – Stainless Steel piping replaced by carbon steel	Guess – No. of new repairs performed = 1000	$= 1000/25000 + 1000$	40×10^{-3}
	No. of repairs performed since opening of plant = 25 000		
5 – No computerized warning systems – human detection	Guess – No of failures detected by staff = 20000	$= 2000/20000 + 2000$	90.9×10^{-3}
	No. of failures missed during inspections = 2000		
6 – No unit storage tank	Guess: No unit storage tank fitted to check purity therefore assuming check performed once a week during 5 years $52 \times 5 = 260$	$= 260/1825$	142.4×10^{-3}
	System would fail once every week day over 5 year period = $365 \times 5 = 1825$		
7 – Ineffective water spray system	Guess: System would fail to suppress gases due to design error associated with height in MIC area which represented area only 1/5000 of plant	$= (1/5000) / 1825$	109.6×10^{-9}
	System failed in MIC area on day over 5 year period of MIC production = $365 \times 5 = 1825$		
8 – Quality of safety devices reduced	Assumptions: reduced quality of safety devices resulted in 50% increase failure rate		16×10^{-3}
	Guess Previous Pf value = 8×10^{-3}		
9 – Quantity of safety devices reduced	Assumption: number of devices Reduced by 25% therefore Pf value increased by 25%		10×10^{-3}
	Guess: Previous Pf value = 8×10^{-3}		
10 – No redundancy (flare tower)	Two built in USA plant, 1 installed in India. Item under maintenance for	$(1/2) / 43800$	11.4×10^{-6}
	Duration of use of single flare tower over 5 years = $24 \times 365 \times 5 = 43800$ hours		

11 – Incapable of dealing with quantity of gases¹	System not designed to deal with volume of gases. Therefore the system failed to handle this volume of gas for 2.5 hours (time of disaster)	2.5/43800	57.1×10^{-6}
	Duration in hours system operating over 5 years = $24 \times 365 \times 5 = 43800$ hours		
12 – Refrigeration unit shut down	Unit shut down for past year = 365 days	365/1825 + 365	166.3×10^{-3}
	MIC production over last 5 years = $365 \times 5 = 1825$		
13 – Plant manning levels reduced	Overall 20% reduction of staff in 4 years	(20/100)/ 1460	136.9×10^{-6}
	Duration = $365 \times 4 = 1460$ days		
14 – Reserve MIC storage tank allowed to be used	Assumption: MIC storage tank used for 50% of time	(50/100) / 1825	273.9×10^{-6}
	Duration of use = 5 years = 1825 days		
15 – Plant being operated outside design parameters	Assumption: 10% of plant being operated outside design parameters for 5 years.	(10/100)/1825	54.8×10^{-6}
16 – No emergency planning procedures	No Emergency planning in place – operation failed on day	1/1825	0.55×10^{-3}
	5 years of MIC production at plant = $5 \times 365 = 1825$		
17 – Lack of notification of incident by plant management	No Emergency planning in place – operation failed on day	1/1825	0.55×10^{-3}
	5 years of MIC production at plant = $5 \times 365 = 1825$		
18 – Alarm siren turned off – Management decision	No. of hours siren turned off = 2		
	No. of hours available for use = $24 \times 365 \times 5 = 43800$	2/43800	45.7×10^{-6}
19 – Defective blow down valve in MIC tank	Total number of days Defective in past 5 years = 12	12/1825	6.6×10^{-3}
	Total number of days in 5 years = 1825		
20 – Substitute engineering solution used “Jumper line”	No of times procedure used = 150	150/ 450 +150	250×10^{-3}
	Number of flushing operation = 450		
21 – Defective gauges not repaired	Guess: No. of gauges defective or still in use = 1320	1320/1320 + 6000	180.3×10^{-3}
	Total number of gauges on plant = 6000		
22 – Slip blind process omitted	Guess: No of procedures requiring slip blinds but not used = 50	50/220 + 50	185.1×10^{-3}
	Total number of procedures requiring slip blinds = 220		
23 – No checking of related lines	Guess: No. of times procedure required during maintenance in 5 years = 300	300/15000 + 300	19.6×10^{-3}
	Total number of maintenance procedures in 5 years = 15 000		

Table 1 Estimated 'Probabilities of Failure' for contributory events' (MIC production assumed to have commenced in 1979, i.e. five years before disaster)